

Arc Flash Requirements

NFPA 70E and NEC state that facilities must provide:

- Safety Program with defined responsibilities
- Analysis for arc flash hazard degree
- Training for workers
- Personal protective equipment (clothing) for workers
- Tools for safe work
- Warning labels on equipment